



BOX MEASUREMENTS

BMS20 ADV
Striking BACK

2005-03-02:07

Content 20 pc



 = Printing area with 3 mm overlap/bleed
Please do NOT make white spaces for glue & striker

Design/Text areas
= sufficient margin to cut & crease

